



Service information

Reference no.: SDA_113412

Symptom

Mandatory Action: Insert a seal between the lids in all repairs for Minuto family machines.

Cure

Cure:

In all Minuto machines a seal has been inserted between the lids to avoid that water can invade the coffee container,

from:

S.N. TW901620280433 only for Philips 3000V2;

S.N. TW901621296282 for all Minuto machines except Philips 3000V2.

Actions: For following S.N.:

Up to S.N. TW901620280432 only for Philips 3000V2;

up to S.N. TW901621296281 for all Minuto machines except Philips 3000V2.

Insert mandatorily the seal, code 421944067611 "BLK SEAL CONT.LIDS SMRG", between the lids as shown below:

Image1



Image2



Image3



Note: for Minuto machines, that mount the coffee lid with seal (see image 4), do not insert a seal between the upper lids.

Image4



ADDITIONAL INFORMATION:

SERIAL NUMBER (First serial where solution has been implemented in production):
From S.N. TW901620280433 only for Philips 3000V2;
From S.N. TW901621296282 for all Minuto machines except Philips 3000V2.

IPM NUMBER (Philips Integrate Problem Management documentation reference number):
107740 (Minuto)

INFORMATION FOR CONSUMER:
None

HISTORY:
14/06/2016 - fourth release - Added "note" and Image4
10/06/2016 - Third release - Change the question and deleted the content
25/05/2016 - Second release: Change action
23/05/2016 - First Release