



**Service information**

**Reference no.: GDA\_105704**

**Symptom**

3 way solenoid valve removal

**Cure**

**INFO:**

The 3 way solenoid valve has been removed from the following Intelia coffee machine produced by September 2013:

10004081 882875304470 HD8753/04 INTELIA CAPP. BK SL 220 KR  
10003884 882875311220 HD8753/11 INTELIA CAPP. BK BK 230 WE  
10004079 882875312160 HD8753/12 INTELIA CAPP. BK BK 230 CH  
10004082 882875315710 HD8753/15 INTELIA CAPP. BK SL 220 CN  
10004085 882875319010 HD8753/19 INTELIA CAPP. BK BK 230 CEE  
10004080 882875323530 HD8753/23 INTELIA CAPP. BK SL 240 AU  
10004233 882875325530 HD8753/25 INTELIA CAPP. SS 240 AU  
10003987 882875381010 HD8753/81 INTELIA CAPP. BK SL 230 WE  
10004109 882875382160 HD8753/82 INTELIA CAPP. SS 230 CH  
10004106 882875383010 HD8753/83 INTELIA CAPP. SS 230 WE  
10004228 882875384010 HD8753/84 INTELIA CAPP. BK SL 230 CEE  
10004100 882875388150 HD8753/88 INTELIA CAPP. BK SL 240 UK  
10004108 882875389010 HD8753/89 INTELIA CAPP. SS 230 CEE  
882875371010 HD8753/71 INTELIA CAPP. BK PSL 230 WE  
  
10004207 882875395010 HD8753/95 INTELIA CAPP. EVO BK PSL 230 WE  
10004223 882875396010 HD8753/96 INTELIA CAPP. EVO SS 230 WE  
882888409010 HD8884/09 INTELIA CAPP. EVO SS 230 CEE  
  
10004224 882875411010 HD8754/11 INTELIA EVO LATTE SS 230 WE  
10004226 882875413530 HD8754/13 INTELIA EVO LATTE SS 240 AU  
10004225 882875419010 HD8754/19 INTELIA EVO LATTE SS 230 CEE

**HISTORY:**

13/06/2014 - First review