Reference no.: GDA_113455



Service information

Symptom

Steam out procedure not mandatory

Cure

Cure:

In the machines indicated below, is no longer mandatory to carry out the steam out procedure because, due to the improvements made to the component's machines, their functional characteristics are unchanged after a freeze-thaw test.

Machines affect to GOA:

• Minuto Family (all platform);

• Incanto Family New;

• Pico Baristo;

• Gran Baristo Family;

- Intelia V2; Philips 2000–2100; Incanto Executive; Moltio Family (all Platform).

Actions:
Follow the instructions of "Repair Flow" attached.
For machines with activated AquaClean filter please note: In case the steam out procedure is done, descale the machine and provide a new filter to the consumer.
Code: 421944050461 ACC SAE WATER FILTER LGV 1UNIT EU.

ADDITIONAL INFORMATION: SERIAL NUMBER (First serial where solution has been implemented in production): None

 $\begin{tabular}{ll} \textbf{IPM NUMBER} & \textbf{(Philips Integrate Problem Management documentation reference number):} \\ \textbf{None} & \\ \end{tabular}$

INFORMATION FOR CONSUMER: None

HISTORY: 13/05/2016 - First Release