



Service information

Reference no.: GDA_113980

Symptom

Wiring for programming with SSC2 is breaking.

Cure

CURE:

To avoid repeated failure to frequent use of the wiring (Image1) it has been created a reinforced wiring (Image2).

Action:

In case of frequent use, order the reinforced wiring (Image2)

Please note: The reinforced wiring does not fit on some machines (Xsmall and Intelia Cappuccino) because inflexibility. For these machines then use the standard wiring (Image1).

Codes:

Standard Wiring (Image1): **11010304 421941192471 WIRING SERPROG PROGRAMMER ASSY**

Reinforced Wiring (Image2): **421941309861 WIRING REINFORCED SSC PROGRAMMER ASSY**



ADDITIONAL INFORMATION:

SERIAL NUMBER (First serial where solution has been implemented in production):

None

IPM NUMBER (Philips Integrate Problem Management documentation reference number):

None

INFORMATION FOR CONSUMER:

None

HISTORY:

30/06/2016 - First Release