

Service information

Symptom

Reference no.: GDA_97831

On/Off switch removed

Cure

INFO: The on/Off switch on the HD7751/00 and HD7753/00 has been removed again. Per WK1248 there is no longer a On/Off switch on the back side of the appliace. Also the information in the DFU has been adapted.

Because the appliance is now permanently connected to the power outlet (cannot be switched off completely), the Stand-by power consumption has been reduced to 0,5W.