



Service information

Reference no.: SDA_102379

Symptom

NEW WATER CONTAINER

Cure

INFO:
Flood of water from the bottom of the appliance while inserting the tank due to the customer.

CURE:
En case of the flood of water from the bottom of the appliance while inserting the tank, replace the old water thank with a new code 421941302721.
In the new water thank has been added 3 centering ribs beside a water thank valve (see Image 1).

Image 1

