



Service information

Reference no.: SDA_105166

Symptom

The machine does not recognize the presence of the drip tray

Cure

INFO:
Sometimes the display shows the message "INSERT DRIP TRAY" although if the drip tray is properly inserted.

CURE:
Replace the sensor reed . 17800442 (996530073661) as shown in Image 1.
Insert the sensor reed from the top to the bottom as shown in Image 2-3-4.

Image 1




Image 2



Image 3



Image 4



HISTORY:
13/05/2014 - First Release