



Service information

Reference no.: SDA_105510

Symptom

Improvement of the gap between the side panel and the front panel on Granbaristo


Cure


INFO:

The display support was changed by inserting two hooks to improve the gap between the side panel and the front panel. See Picture 1

CURE:

The side panels assembled in the previous machines are not compatible with the new support. To use the new display support on the machines up to TU901419067670 it's necessary to remove the two hooks as shown in Picture 2 and 3.





HISTORY:
28/05/2014 - First review