



Service information

Reference no.: SDA_106616

Symptom

Minuto: the BU is difficult to reinsert

Cure

INFO:

The coffee residues drawer has been improved in order to facilitate the insertion of the Brew Unit into the machine.

CURE:

From sn TW901425363901, to facilitate the slide and the clamping of the BU into the appliance, the coffee residues drawer (12NC 421944008911) has been improved by adding two ramps on it (Image 1) .

image1



SERIAL NUMBER:
From S.N. TW901425363901

IPM NUMBER:
96211

FAQ NUMBER:
General FAQ published on "How to remove and reinsert the brew group" for Minuto. E38_MINUTO_BREWUNIT_99469

INFORMATION FOR CONSUMER:
No

REMARK:
30/07/2014 - First Release