



Service information

Reference no.: SDA_106978

Symptom

Smoke/smell of the Motor Unit

Cure

INFO:

Smell and smoke occurrence of the Motor unit due to a defect commutator.

Cure:Improvement of the motor unit implemented in WK1421 onwards

Scrap of old motor stock 4203-035-96941 or send old stock back to the supplier for exchange.

Only used motor unit should be the following 12 NC : 4203-036-01831 (for China market the latest 12 NC version is: 4203-036-08621)