

Service information

Symptom

Reference no.: SDA_108070

GC76xx Product behavior upon cartridge exhaustion and replacement

Cure

The attached material intends to address in detail, how the GC76xx behaves upon cartridge exhaustion and cartridge replacement. Furthermore, the recommendations to users in the event of queries regarding this topic.