



Service information

Reference no.: SDA_108477

Symptom

Appliance cannot switch on

Cure

SYMPTOM:
It is not possible to switch on the appliances FC918x - FC919x

Reason: on/off switch is deformed.

CURE:
New switch can be replaced on the PCB board.
Switch has been added to Sboms and Serv. Manuals :

SWITCH NOVA KAN-J4(B)-33 / code is 4322 006 09921.