Reference no.: SDA\_108804



### Service information

## **Symptom**

Vibration and noise inside the machine Minuto family.


### Cure

**Symptom:** The boiler and boiler support fixing screw is not tight in the proper way. This is causing vibration and noise.

 $\label{lem:cure:cure:cure:cure} \textbf{Cure:} \\ \textbf{Check that the fixing screws both for the boiler and boiler support (Image1 ) are properly tightened from SN $$\mathbf{TW90144738197}$.$ 

# Action:

Up to SN **TW90144738196** tighten the screws in the boiler and boiler support (Image1) Image1



ADDITIONAL INFORMATION: SERIAL NUMBER (First serial where solution has been implemented in production): TW90144738197

IPM NUMBER (Philips Integrate Problem Management documentation reference number):  $102735\,$ 

# INFORMATION FOR CONSUMER:

## HISTORY:

15/07/2016 - third Release: Modified the CURE and Actions. 05/11/2015 - Second Release: Modified the picture. 02/12/2014 - First Release