



**Service information**

**Reference no.: SDA\_109038**

**Symptom**

Motor change from JK back to CCL motor (HR1869-76)

**Cure**

**INFO:** Smell and smoke occurrence of the JK motor unit  
important: this document replaces the symptom cure SDA\_106978 from August 2014

**Cure:**  
change of the JK motor back to the CCL motor in the Juicers HR1869-76

the JK motor 4203 036 01831 must be scrapped  
and is replaced by the  
CCL motor 4203 035 96941 in all markets, expect UK country.  
for UK we get a new motor in April.

for the China market please use the new code 420303609911.