



Service information

Reference no.: SDA_109625


Symptom

White Support boiler in GranBaristo family.

Cure

INFO:

From s.n. TU901446163585 to s.n.TU901510056621 you may see the white boiler support (Image1). It has been temporarily introduced to counteract the premature wear of the piston seals.



CURE:

From s.n. TU901446163585 to s.n.TU901510056620

To replace the white support order only the cod. 421944032332 BLK PISTON UNIT UPPER PART SUPP.V3 CST

To replace the black support order only the cod. 421944032331 BLK PISTON UNIT UPPER PART SUPP.V2 CST

The 2 parts cannot be switched.

ADDITIONAL INFORMATION:

SERIAL NUMBER (First serial where solution has been implemented in production):

From s.n.TU901446163585 to Tu901510056621

IPM NUMBER (Philips Integrate Problem Management documentation reference number):

None

FAQ NUMBER (for Call Center reference):

None

INFORMATION FOR CALL CENTER:

None.

INFORMATION FOR CONSUMER:

None.

HISTORY:

12/03/2015 - First Release

22/04/2015 - Second release