



Service information

Reference no.: SDA_109701

Symptom

Improve the discharge pressure of the hydraulic circuit in Minuto.

Cure

INFO:

A new pin boiler and brew unit 5bar (with the changed spring) has been inserted to improve the discharge pressure of the hydraulic circuit.

CURE:

The following components:

- BLK PIN FOR BOILER VALVE 4BAR ASSY. Cod. 421946011491
- BLK BREW UNIT 8GR.5BAR XS4 Cod. 421944028471

have been inserted on:

- Minuto AMF and CMF inserted from SN TW901441664668
- Minuto OTC inserted from SN TW901436526727

ADDITIONAL INFORMATION:

SERIAL NUMBER (First serial where solution has been implemented in production):

Minuto AMF and CMF inserted from SN TW901441664668
Minuto OTC inserted from SN TW901436526727

IPM NUMBER (Philips Integrate Problem Management documentation reference number):

None

FAQ NUMBER (for Call Center reference):

None

INFORMATION FOR CALL CENTER:

None

INFORMATION FOR CONSUMER:

None

HISTORY:

05/05/2015 - Second Release (added new CTNs)
20/03/2015 - First Release