



Service information

Reference no.: SDA_110560

Symptom

Clamp improvement - Texas/Mexico Juicer family (HR183x, HR185x, HR186x)

Cure

INFO: Texas/Mexico Juicer Family is facing increasing FCR due to breaking clamp levers.

CURE: below existing clamps are replaced and exchange by new 12NC's.

HR183x: 420303610741 replaces 420303603001

420303610751 replaces 420303602781

HR185x, HR186x: 420303610711 replaces 420303600921

420303610721 replaces 420303601351

420303610731 replaces 420303607631

Important: Existing stock must be scrapped