

Service information

Symptom

Reference no.: SDA_111441

Wrong stock of PCB's

Cure

SYMPTOM :

Wrong PCB's on stock for all F8700, FC8710, FC8810, FC8820 appliances.

INFO: Please donot replace the PCB's of above appliances untill we have the information which PCB's are correct and are on stock. Also the PCB's need to be callibrated, information of the way of working will be send in wk. 1539.

We expect to have the correct information of 12NC's and stock from wk.1539 onwards.