



Service information

Reference no.: SDA_112164

Symptom

Poor soleplate Gliding issue for GC6601 GC6602 GC6605 GC6608 and GC6611

Cure

Symptom : Poor soleplate Gliding issue for GC6601,GC6602, GC6605,GC6608 & GC6611

Root Cause: Iron Performance issue, " Customer dissatisfy with the device Gliding , iron does not slide along while ironing and does not glide properly"

Solution : Change Non-stick coating soleplate to a Ceramic soleplate

Note: Only change if GC6601, GC6601,GC6605, GC6608 & GC6611 soleplate Non-stick coating is damaged.

**Non Stick Coating
Soleplate
(996510070249)**



Change Non-stick coating
soleplate to a Ceramic
soleplate



**Ceramic Coating
Soleplate
(996510070267)**

