



Service information

Reference no.: SDA_112179_E97_GRIND_BREW

Symptom

Uae up old valve motor in HD7765 & HD7766 models

Cure

INFO:

Models HD7765 & HD7766 the design of valve motor slightly changed.
For the new models the wires/connector is on top of the valve motor, for the old type the wires/connector is located on the side of the valve motor.

CURE:

Continue to use the old valve motor 12nc 996510064761 as the old/new valve motors are interchangeable as long you replace the valve motor including wiring/connector.

ADDITIONAL INFORMATION:

IPM NUMBER (Philips Integrate Problem Management documentation reference number):
IPM-114007

FAQ NUMBER (for Call Center reference):
None

INFORMATION FOR CALL CENTER:
None

INFORMATION FOR CONSUMER:
None

HISTORY:
24-11-2015 - First Release