



Service information

Reference no.: SDA_113908_E97_G_B_LOCKER

Symptom

Locker assembly cleaning window broken

Cure

INFO:

Models HD7761, HD7762, HD7765 & HD7766 the locker assembly cleaning window is broken/too brittle.

Improvements:

1. WK1619 molding parameters improved.
2. WK1629 improved material composition and improved production tool.

CURE:

Exchange loader assembly 9965 100 75345

ADDITIONAL INFORMATION:

IPM NUMBER (Philips Integrate Problem Management documentation reference number):
IPM-117907

FAQ NUMBER (for Call Center reference):
None

INFORMATION FOR CALL CENTER:
None

INFORMATION FOR CONSUMER:
None

HISTORY:
27-06-2016 - First Release