



**Service information**

**Reference no.: SDA\_113952**

**Symptom**

FC919x - whistling sound

**Cure**

**SYMPTOM:**  
When switching on the appliances FC919x sometimes a whistling sound can be heard.

**INFO:**  
It appears that this sound can occur with the appliances which have the old Exhaust Sealing (before November 2015).  
This can happen with all FC919x- and FC918x - appliances

**CURE:**  
When a whistling sound occurs, the Exhaust Sealing need to be replaced.  
Exhaust sealing has code 4322 001 75293 , this is available per wk. 1626 and can be ordered.