



Service information

Reference no.: SDA_77094

Symptom

Repair Kit Solution for HP6481-83/00

Cure

Due to the fact, that broken gearwheels at old epilator types HP6481-83/00 are still the reason for high Costs of Non Quality, we decided, to make an additional Repair Kit available, so that repairs can be done on the concerned types. To do so, some preparation at Epilation heads and Driving unit has to be done (change of the old Gearwheel 3 and support plate).

See attached instruction sheet.
This sheet is also attached to all related s-manuals.

Best regards Joachim Warmuth