

Service information

Symptom

Reference no.: SDA_79858

change service strategy to repair in HR1361-66/00 Handblender

Cure

INFO:

the service strategy is changed from exchange to repair in all Boxter handblenders HR1361-66/00.

CURE:now it is possible to exchange for different countries below parts: - Motor Assy + coupling - PCB Assy + knobs + switch - Power unit Assy for TR, TW, CN, KR market see also attached s- manuals in this sympton cure the service manuals are also uploaded to the Intranet.