



**Service information**

**Reference no.: SDA\_83432**

**Symptom**

Leakage from faucet in Talea, Odea, Eclipse, Spidem My Coffee and Gaggia Platinum

**Cure**

INFO:  
Leakage from the faucet assembly.

CURE:  
In the case of leakage, replace the faucet assembly, part code 11008698, with the faucet assembly, part code 11025775, signed with a black dot (image 1). The o-rings inside the faucet assembly have been improved. Spare part warehouse has been updated; also the old faucets (part code 11008698) were re-worked and are signed with two black dots.

