



### Service information

Reference no.: SDA\_83497

### Symptom

Hoses can be pulled too easy out of appliance

### Cure

#### INFO:

Affected Production (Year/week nr)

Year / week nr from WK1018 till WK1026 are affected, but also appliances from WK1026 till WK1040 can present with a similar failure of the hose lock. It can be that a recently repaired appliance has been equipped with a defective hose. There are no spare parts stocks in the warehouse, because of this problem. New stocks are expected in WK1044

#### CURE:

Replace the total hose assy (spare part stock not affected)

Model:	Description:	Part: 12nc	S/M Pos:
FC9302/01	Hose/Swivel/Bend assy	4322 005 08191	48
FC9304/01	Hose/Swivel/Bend assy	4322 005 29121	48
FC9306/01/02	Hose/Swivel/Bend assy	4322 005 27041	48
FC9308/01	Hose/Swivel/Bend assy	4322 009 00351	47

