



**Service information**

**Reference no.: SDA\_84406**

**Symptom**

Cordwinder not operating

**Cure**

INFO:  
Cordwinder is not operating. .

CURE:  
To solve this issue, replace the Cordwinder lever (pos. 16 on Service Manual) with a modified version.  
See enclosed pictures.  
Partnumber of Cordwinder lever 4222 459 47271

Product Model/Chassis:  
FC8912 – FC 8918