



Service information

Reference no.: SDA_85898

Symptom

change from Whisk Beater to Twin Beater in HR7774-75/00

Cure

INFO:

change due to quality problems with the whisk beaters in the products HR7774-75/00

CURE:

change from Whisk Beater to Twin Beater in HR7774-75/00

HR7774:

status old till KW 0915

status new since KW 0916

HR7775:

status old till KW 0921

status new since KW 0922

REMARK:

see also attached service manuals