



Service information

Reference no.: SDA_85922

Symptom

Coffee powder leakage caused by broken/detached conveyor

Cure

INFO:

Coffee powder leakage because of broken or detached conveyor in Incanto, Talea, Odea, Primea, Privileg Cafè Crema, Xsmall, Syntia, Spidem My Coffee, Espresso Italiano, Xelsis, MST Caruso, Spidem Flavia, Exprelia, Gaggia Platinum, Gaggia Brera, Gaggia Unica, Gaggia Cappuccino and Gaggia Accademia.

CURE:

Replace the conveyor (image 1) of coffee grinder assembly by the strenghtened conveyor, part code 11026355 (image 2). Strenghtened areas shown in image 2.

Image 1



Image 2

