



### Service information

Reference no.: SDA\_89999

### Symptom

Mandatory - Replacement black coupling plate brew unit

### Cure

#### INFO:

The coupling plate brew unit not seek the presence of micro brew unit.

Models concerned:

[Intelial Cappuccino serial number 10003884](#)

From serial number TU901139127149 to serial number TU901139127588

From serial number TU901140129864 to serial number TU901140130638

From serial number TU901142138631 to serial number TU901142138632

[Intelial Cappuccino serial number 10003987](#)

From serial number TU901140134542 to serial number TU901140134807

From serial number TU901141134768 to serial number TU901141134776

From serial number TU901141134817 to serial number TU901141135389

#### CURE:

Replace the brew unit code 11012382 having a black "coupling plate" (Image 1), with the brew unit code 11028890 having a grey "coupling plate" (Image 2)





Image 2