



Service information

Reference no.: SDA_91765

Symptom

Mandatory- New top of upper cover casing in Gaggia Brera

Cure

INFO:

Possible cracking of chromium in the coverage of the steam wand in Gaggia Brera up to serial number TU9011029097424. The plastic chrome cover on the steam wand has been removed in the new Gaggia Brera production line, to avoid excessive clearance between the casing cover and steam wand, we also lowered the hole in the cap.

CURE:

Remove the cover and insert the new cap with the smaller hole code 11027517. Also give the customer the attached sheet (pdf file attached) which gives an explanation about the piece which has been removed.

