



please remove it, as interference can still accidentally trigger the two-cup button. The header on the interconnect PCBA must remain empty!

REMARKS:

03-04-2012: Initial version

15-06-2012: Making a jumper removed, not a definite solution, S/W upgrade is necessary

19-11-2013: added forced NSE