



Service information

Reference no.: SDA_95700

Symptom

(New) Bread pan does not fit

Cure

SYMPTOM : From production **week 1208** a new bread pan is supplied, this new bread pan does not fit onto the old motor assy. The **new bread pan with service number 9965 100 55821** is also supplied, even when ordering the old one under service number 4222 459 45779!

CURE: When replacing the bread pan, **the old motor assy (4222 459 52291) should be replaced as well by a new one (under service number 9965 100 55822).**

REMARK: Due to no stock of the old bread pan (4222 459 45779), it is to be decided locally if repair is economic feasible, since a **new motor assy (9965 100 55822) should be ordered in any case.** This is an expensive repair!



NEW BREAD PAN



OLD BREAD PAN