



Service information

Reference no.: SDA_96858

Symptom

PCBA does not fit in Motorhousing

Cure

SYMPTOM :
PCB does not fit in Motorhousing

INFO:
In December 2012 a modification took place on these 2 components.
The components are not interchangeable.
New PCB only fits on new Motorhousing.
Modification was done on the Heatsink of PCB
In the attached file the modification has been explained

CURE:
No stock available anymore of old PCB 4322 006 24701, stock
of old motorhousing with 12NC 9965 100 51309 should be scrapped.

IMPORTANT REMARK :
Repair should take place only with new PCB assy 4322 006 24702
together with new Motorhousing 9965 100 61664 !