



Service information

Reference no.: SDA_96986

Symptom

New sw for Xelsis

Cure

INFO:

New software with changed hardware configuration in standby mode.

CURE:

Upload the new software V.01.05.01

In Detail:

- New standby handler, in order to reduce the power consumption.
- Added two software thermostats to give no power to coffee boiler and steam boiler when its boiler temperature reach respectively 140°C and 160°C.