Service information

Reference no.: GDA_105015

Symptom

New software for Intelia Cappuccino.

Cure

INFO:
New software V03.06.01 for heater driver improvement in order to stabilize coffee and water temperatures.
Remark: only for machine with a single solenoid valve From S/N TU901335143352.

HISTORY:
24/04/2014 - First Release