Service information

Symptom

On/off button of FC876x model is not working

Cure

SYMPTOM:
On/off button is not working in FC876x-models

CURE:
Improvements have been done to avoid this problem.
Correct buttons are available from wk. 1346 onwards,
codenumber of this button : 996510051301

INFO:
The dome which pushes the switch has been enlarged
to be sure that switch will be touched, see enclosure.

Modification on on/off button FC876x-models : dome has been enlarged