**Service information**

**Reference no.: SDA_90710**

# Symptom

Programing for Xsmall and My Coffee (Eng).

# Cure

INFO:
Programing for Xsmall and My Coffee.

CURE:
These lines have no infrared interface. The machines must program with the infrared cable 11010304.
To program and diagnose mode it is necessary to open the cover. The interface for the cable is on the CPU board.

**Please see the atacched file in Eng.**