Service information

Reference no.: SDA_97554

Symptom

NEW SOFTWARE FOR INTELIA CAPPUCCINO AND INTELIA EVO CAPPUCCINO

Cure

INFO:
New software to delete the warning of the carafe presence before dispensing cappuccino and for restore the "one touch" cappuccino function.

CURE:
Upload the new software V. 01.07.01.
In detail:
Warning carafe deleted.
Restored "one touch" cappuccino function.
Attached the additional sheet "Customer Information - New software for Intelia Cappuccino" :a copy has to be provided to the Consumer after this uploading of the new software.