



**Service information**

**Reference no.: GDA\_104726**

**Symptom**

Additional seal found in boiler assy.

**Cure**

INFO:  
From S/N TU901342179781 in the Piston Unit Assy a seal has been inserted in order to improve the boiler assy.  
In Image 1 you can see the Piston Unit without seal.  
In Image 2 you can see the Piston Unit with seal.  
Both versions can be used for repair.

Image 1



Image 2



History:  
31-03-2014: First Release