



Service information

Reference no.: GDA_106613


Symptom

New Flow Meter Connector in production.

Cure

INFO:

Was added to the new connector in the flow meter to improve seating (Image1) from S.N. see below (SERIAL NUMBER).



SERIAL NUMBER:

Intelia S.N. TW901406097123
Moltio S.N. TW901409158277
T-Rex S.N. TW901423323373
XSmall S.N. TW901411190458
Intuita S.N. . TW9014071110373
Minuto S.N. TW901406092695
Moltio Caraffa S.N. TU901411040344
Intelia Caraffa S.N. TU901414052051

IPM NUMBER (Philips Integrate Problem Management documentation reference number):

None.

FAQ NUMBER (for Call Center reference):

None.

INFORMATION FOR CALL CENTER:

None.

INFORMATION FOR CONSUMER:

None.

HISTORY:

07/03/2016 - Third Release Deleted Xelsis _ Created SDA 112895 Mandatory for Exprelia, Xelsis an Gaggia Accademia
25/02/2016 - Second Release Deleted Exprelia - Created SDA 112895 Mandatory only for Exprelia
29/07/2014 - First Release