



Service information

Reference no.: GDA_113605

Symptom

Changes Piston for Xsmall, Philips 2000 and Philips 2100

Cure

CURE:

From **WK 15-2016** changes the color of the piston of the brew unit from black to gray (Image 1) making it more recognizable from consumers to perform lubrication.

Image 1



From S.N. TW901546609698 order the cod. 421944065811 GRY BREW UNIT 8GR.INT.PISTON GEN.V3 ASSY.
Up to S.N. TW901546609697 order the cod. 11023086 BLK BREW UNIT 8GR.INT.PISTON GEN.ASSY.

ADDITIONAL INFORMATION:

SERIAL NUMBER (First serial where solution has been implemented in production):
From S.N. TW901546609698

IPM NUMBER (Philips Integrate Problem Management documentation reference number):
None

INFORMATION FOR CONSUMER:
None

HISTORY:
18/05/2016 - First Release