



Service information

Reference no.: GDA_85692

Symptom

HR7761,HR7762,RI7761: bowl & lid performace upgrade and matching issues

Cure

There are some updates on the bowl, lid & shaft starts from WK1203 to WK1220 which are related to performance and also bowl & lid matching issues.

There are 3 parts matching are co-related(pos 7,8 & 10), therefore we request to repair them in 1 set in the future, you can use up existing stocks before implement this change.

3 parts information:

Pos	12NC	Description	Remark
7	996510051823	BOWL LID	
8	996510051813	BOWL	
	996510052996	BOWL BLACK	FOR HR7762/90, HR7762/91
10	996510051824	TOOL HOLDER	
	996510052993	TOOL HOLDER BLACK	FOR HR7762/90, HR7762/91

New combined part information:

Pos	12NC	Description	Remark
7	996510057295	BOWL,BOWL LID&TOOL HOLDER	
	996510056881	BOWL,BOWL LID&TOOL HOLDER BLACK	FOR HR7762/90, HR7762/91

Now the combined part have a change : Spray paint handle cover & lid cap changed from spray paint to in-mould color, so the 12NC updated as below:

Pos	12NC	Description
7	9965 100 60717	BOWL,BOWL LID&TOOL HOLDER
	9965 100 60716	BOWL,BOWL LID&TOOL HOLDER BLACK

Pictures:

