



Service information

Reference no.: GDA_97841

Symptom

Extreme smell of plastics

Cure

Symptom:
New appliances have an extreme smell of plastic

Cure:
INFO:
When opening the box, an extreme smell of plastic appears.

CURE:
The rubber parts are now purchased from another supplier who treats the rubberparts in a different way.
The extreme smell has disappeared

REMARK:
All models from production week 1312 and later donot have this smell anymore.