



Service information

Reference no.: SDA_101247

Symptom

FC9910 switch off by itself

Cure

SYMPTOM:
HomeRun FC9910 switches off by itself after 10-20 minutes operating.

INFO:
If appliance switches off by itself and cannot be restarted anymore, most of the time the pcb of battery is the cause.

CURE:
Change the Battery : pos. 12 in Service Manual : 4222 459 52841