



**Service information**

**Reference no.: SDA\_101895**

**Symptom**

Appliance steams after switching on

**Cure**

**INFO:**

With the implementation of the new layout for the steam circuit, the one-way valve after the steam-pump had been eliminated. Somehow still water finds its way through the steam pump into the thermoblock, even when not in use. When the appliance is being switched on after the appliance has not been used (even for a limited amount of time), this water will be boiled and turned into steam by the heating of the thermoblock.

- HD7853 appliances /B
- HD7854/60 and HD7854/80 appliances /C (EU)
- HD7854/84, /86 and /88 appliances /B (Brazil & Argentina)

**CURE:**

Reinstate the one-way valve 4222 259 42680 in the steam circuit, as per the instructions in the attached Powerpoint.

**REMARKS:**

- 11-10-2013: Initial version