



**Service information**

**Reference no.: SDA\_102174**

**Symptom**

Water container does not fit snugly wrt back of Senseo

**Cure**

**INFO:**

Due to specific production conditions the water containers supplied from the factory may not fit properly, especially at the top.

**CURE:**

Supply a new water container with the appliance (422225948663).

**REMARKS:**

- 24-10-2013: Initial version