



Service information

Reference no.: SDA_102316

Symptom

New model water container / water level sensor

Cure

INFO:

To improve the quality of the float construction in the water container of Senseo Quadrante HD7863 & HD7864 appliances, the **/B** models have been equipped with a new water container and water level sensor. As the minimum water level in the water container has been increased from 1 to 2 cups, also the software on the Main PCBA has been changed. Change effective from WK1337 onwards.

CURE:

Replace the required parts with the correct equivalent according to the service manual:

- 422225954071 Water container /A
- 422225956281 Water container /B
- 422225943420 Water level sensor PCBA /A
- 422225955911 Water level sensor PCBA /B
- 422225954981 PCB assy main /A
- 422225956311 PCB assy main /B

An alternative solution for a defective /A appliance would be to replace all three components, thereby transforming it to a /B execution (when you do, please mark the appliance by writing "/B" on the serial number label on the bottom of the appliance).

REMARKS:

- 1-11-2013: Initial version