



Service information

Reference no.: SDA_102915

Symptom

Software Update History

Cure

INFO:

XELSIS CLASS:

Slim Boiler from S/N TU901150186484

- 01.05.02 Modified the standby mode to avoid spurious wakeup
- 01.05.01 Modified the standby mode to reduce power consumption and overheating solved
- 01.04.13 Descaling cycle through the brew Unit valve
- 01.03.11 First release

Standard Boiler Up to S/N TU901150186483

- 01.03.02 Modified the standby mode to avoid spurious wakeup
- 01.03.01 Descaling cycle through the brew unit valve
- 01.02.13 Less coffee powder behind /under the BG
- 01.01.05 New descaling indication management
- 01.00.44 Enabled to memorize the coffee length by pressing the coffee key - as usual
- 01.00.41 First release

XELSIS FOCUS:

- 01.08.00 Modified the standby mode to reduce power consumption and overheating solved
- 01.07.01 Descaling cycle through the brew unit valve
- 01.06.27 Check of beverage parameter ranges before product dispensing
- 01.06.21 Soft switching on/off of key backlight
- 01.06.17 First release

XELSIS ID:

Slim Boiler from S/N TU901150186484

- 02.08.04 Correction stand by function
- 02.08.01 Overheating solved
- 02.07.03 Descaling cycle through the brew unit valve
- 02.06.11 First Release

Standard Boiler Up to S/N TU901150186483

- 02.05.13 Less coffee powder behind /under the BG
- 02.04.05 First release

CURE:

Update always the new software available in SSC.

HISTORY:

17/03/2014 - First Review : added SW 01.03.02 for Xelsis Class - Standard Boiler - Up to S/N TU901150186483

12/12/2013 - First Release