



**Service information**

**Reference no.: SDA\_103523**

**Symptom**

Mandatory: insert sheet cleaning coffee powder duct Minuto

**Cure**

**INFO:**

The machine may not working properly because the coffee powder duct (shown by the arrow in Image 1) become clogged.

**CURE:**

From S/N TW901406092406 the new additional sheet code 421946011131, with the instruction for cleaning coffee powder duct, has been inserted.

In all machine that return to workshop for any reason up to S/N TW901406092405, insert the additional sheet code 421946011131 that you find in the attached file.

Image 1

